



**Rockwell
International**

Collins instruction book

Part 2

851S-1 Receiver

Part 2 of this instruction book includes:

<i>Power Supply</i>	<i>523-0767948</i>	<i>Synthesizer Reference</i>	<i>523-0767970</i>
<i>LED Status Display</i>	<i>523-0767946</i>	<i>Synthesizer End Decade</i>	<i>523-0767973</i>
<i>Count/Store Assembly</i>	<i>523-0769218</i>	<i>Synthesizer Decade</i>	<i>523-0767972</i>
<i>Frequency Display</i>	<i>523-0767975</i>	<i>Synthesizer Output</i>	<i>523-0767971</i>
<i>VBFO</i>	<i>523-0769219</i>	<i>TS-8010 Card Extender Kit</i>	<i>523-0767968</i>
<i>Receive Audio</i>	<i>523-0767956</i>	<i>Options</i>	
<i>Channel B IF</i>	<i>523-0767965</i>	<i>AC-8012 Oven Standard Kit</i>	<i>523-0768671</i>
<i>Channel A IF</i>	<i>523-0767962</i>	<i>AC-8013 External Standard Kit</i>	<i>523-0768672</i>
<i>Filter</i>	<i>523-0767967</i>	<i>AC-8090 Remote Control Kit</i>	<i>523-0768675</i>
<i>RF Translator</i>	<i>523-0767959</i>	<i>AC-85100 ISB Kit</i>	<i>523-0769222</i>
<i>RF Translator (1/2-Octave RF Filters)</i>	<i>523-0769220</i>	<i>AC-85101 DVBF0 Kit</i>	<i>523-0769223</i>
<i>Control</i>	<i>523-0769221</i>	<i>AC-85102 Decade Expansion Kit</i>	<i>523-0769224</i>
<i>Parallel Input</i>	<i>523-0767949</i>	<i>AC-85105 Optional Filters Kit</i>	<i>523-0769226</i>
<i>Parallel Output</i>	<i>523-0767950</i>	<i>AC-85106 RF Translator Kit</i>	<i>523-0769227</i>
<i>Serial Interface</i>	<i>523-0767951</i>	<i>AC-85108 Channel A IF Kit</i>	<i>523-0769225</i>
<i>Synthesizer Voltage Regulator</i>	<i>523-0767974</i>		

**Collins Telecommunications
Products Division
Electronic Systems Group
Rockwell International
Cedar Rapids, Iowa 52406**

Caution

The material in this manual is subject to change. Before attempting any maintenance operation on the equipment covered in this manual, verify that you have a complete and up-to-date publication applicable to your equipment.

Please be advised that completion of the enclosed Automatic Distribution Service Card and return to Rockwell International ensures you of manual revisions and service bulletin modifications to your equipment. Without the return of this card, Rockwell International bears no responsibility to forward this information to you.

We welcome your comments concerning this instruction book. Although every effort has been made to keep it free of errors, some may occur. When reporting a specific problem, please describe it briefly and include the instruction book part number, the paragraph or figure number, and the page number.

Send your comments to: Logistics
Collins Telecommunications
Products Division
Rockwell International
Cedar Rapids, Iowa 52406

ATTN: Quality Control-Support Engineering 179-200
